

JIN HUAT & CO

176 Sin Ming Drive, #05-01
Sin Ming Autocare
Singapore 575721
Tel : 6453 2151; Fax : 6456 3060
email: jinhuat1951@gmail.com
Co. Reg. No: 020403/00C

Quotation

To: Mr Pang Say Kong
Ms Pang See Leng
16 Jalan Bingka
Singapore 588914
Contact: 9833 3683

Not Not hatched
Returning B4 paint
4 days
\$3577.75

Date : 02 March 2022

Pages : 1 of 1

Vehicle No: SDF 707 R
Model: Toyota CHR
Insurer: UOI Insurance

3rd Party claim SMN 8261 H insured with
AIG Insurance
Date of Accident: 01/03/2022

Items	Description	Qty	Unit	Unit Price	Total Price
	Spare Parts:				
1	Front bumper ✓	1	Bu/comp	\$ 385.00	\$ 385.00
2	LH Front Fender ✓	1	Bu	\$ 325.00	\$ 325.00
3	LH Front Wheel arch garnish ✓	1	Bu	\$ 190.00	\$ 190.00
4	LH Front side retainer ✓		Bu	\$ 59.00	\$ 59.00
5	LH H/Lamp - HID ✓	1	Lamp	\$ 2,140.00	\$ 2,140.00
6	LH H/Lamp bracket holder	1	Brk	\$ 85.00	\$ 85.00
7	LH Front bumper sensor ✓	1	Sns	\$ 235.00	\$ 235.00
8	Front lower spoiler	1	Spn	\$ 216.00	\$ 216.00
9	Front lower side grille cover	1	Grn	\$ 65.00	\$ 65.00
10	Front Bumper Fog Lamp	1	Lmp	\$ 230.00	\$ 230.00
11	Front Bumper Reinforcement - top	1	R	\$ 216.00	\$ 216.00
12	Front Bumper Reinforcement - bottom	1	R	\$ 158.00	\$ 158.00
13	Clips	10	Clp	\$ 1.80	\$ 18.00
	Labour to repair and replace damaged parts				\$ 850.00
	Check wheel alignment			~ ~	\$ 60.00
	Spray painting and underseal (Pearl White)				\$ 900.00
TOTAL PRICE					\$ 6,132.00

JIN HUAT & CO

Alice Tan

[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: