



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 5934B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILLAMP RH	CRACKED	781.00	781.00
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	697.40	-
1	TAILLAMP LOWER APRON	TORN	376.90	376.90
1	REAR RH FENDER TOP GARNISH	MISSING	439.40	439.40
1	REAR RH FENDER GLASS	CUT	931.50	931.50
1	REAR RH FENDER GLASS MOULDING	NECESSARY	155.60	155.60
1	SLIDING DOOR RAIL RH	BENT	384.90	384.90
1	TAILGATE	TO REPAIR SEE LABOUR	1,712.40	-
1	TAILGATE GLASS MOULDING	NOT NECESSARY	185.90	-
1	TAILGATE OUTER CHROME GARNISH	NOT NECESSARY	581.90	-
1	TOYOTA LOGO	NECESSARY	65.00	65.00
1	HYBRID LOGO	NECESSARY	85.00	85.00
	LESS 20% DISCOUNT		-	-643.86
			6,396.90	2,575.44
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR RH FENDER GLASS SEALANT (SN)	NECESSARY	40.00	40.00
1	TAILGATE GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	TAILGATE OUTER CHROME GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
			120.00	40.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILLAMP PANEL RH AND TAILGATE.		800.00	300.00
	SPRAY PAINTING.		800.00	400.00
	WIRING.		50.00	30.00
	TO TRANSFER TAILGATE FITTINGS.	NOT NECESSARY	150.00	-
	TO REPLACE FENDER GLASS.		150.00	60.00
	TO REMOVE TAILGATE CAMERA.	NOT NECESSARY	100.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE TAILGATE GLASS.	NOT NECESSARY	180.00	-
			2,230.00	790.00
GRAND TOTAL			8,746.90	3,405.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,700.00

Report Ref No. CS/LPC22002016/Aty3m4

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.