



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22002016/Aty3m4 Date: 13/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4367K	Veh. Inspected	SMH 5934B	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025506	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	02/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZWR800356872	Colour	WHITE	
Odometer	69242 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	195/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	195/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/02/2022	Inspection Date	12/04/2022	
Survey held at	S L MOTOR REPAIR 1 KAKI BUKIT AVE 6 #01-95 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	