

Car in

28/3/21.

WIP: 13725

Veron

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

LA/



HIGH - Adrian
- 6 days -

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMZ 7820 M

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$ 1,738.00	+
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 220.00	+
3	REAR BUMPER SPOILER <i>cut</i>	1	\$ 510.00	✓
4	REAR BUMPER BRACKET <i>new</i>	1	\$ 53.00	+
5	REAR LIGHT REFLECTOR - LH <i>new</i>	1	\$ 46.00	+
6	REAR BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 71.00	+
7	REAR WHEEL ARCH COVER - LH/RH <i>LH missing, RH 2</i>	2	\$ 566.00	✓
8	REAR FENDER - LH <i>Repair</i>	1	\$ 3,640.00	+
9	QUARTER WINDOW - LH <i>new</i>	1	\$ 683.00	+
10	PRIMER <i>Green</i>	1	\$ 22.00	+
11	REAR END PANEL	1	\$ 329.00	X
12	REAR WHEEL HOUSING LINER <i>new</i>	1	\$ 262.00	+
13	REAR WHEEL SPOILER - LH <i>new</i>	1	\$ 44.00	+
14	REAR DOOR - LH <i>Distorted</i>	1	\$ 3,127.00	✓
15	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 151.00	✓
16	REAR DOOR CATCH - LH <i>Damaged</i>	1	\$ 120.00	✓
17	REAR SILL PANEL SEAL - LH <i>new</i>	1	\$ 151.00	+
18	REAR DOOR COVER - LH <i>cut</i>	1	\$ 270.00	✓
19	REAR DOOR HANDLE - LH <i>Repair</i>	1	\$ 222.00	+
20	REAR DOOR HOUSING - LH <i>new</i>	1	\$ 31.00	+
SUB TOTAL SPARE PARTS			\$ 12,256.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Resurveyed
Adrian Li

SL/S