$51\,UBI\,AVE\,1,\#01-25\,PAYA\,UBI\,INDUSTRIAL\,PARK,SINGAPORE\,408933\,TEL:(065)\,62563561\,FAX:(065)\,62564315$ 

## **Immediate Advice**

To: AXA Insurance Pte Ltd DATE: 17/3/2022

## Survey details

| Date of loss        | 2/3/2022           |
|---------------------|--------------------|
| Date of appointment | 4/3/2022           |
| Date of survey      | 4/3/2022           |
| Location of survey  | SPEEDWERKZ PTE LTD |
|                     |                    |

## **Vehicle Details:**

| Claim Type:          | THIRD PARTY    |
|----------------------|----------------|
| Vehicle number       | GW 6169D       |
| Make and Model       | NISSAN CABSTAR |
| Date of registration | 2/9/2003       |
| Excess               |                |
| Market Value         | \$18,000.00    |
| Parf Rebate          | \$4,345.00     |
| Nett Loss            | \$13,655.00    |

## Repair details

| al Estimate |
|-------------|
|-------------|

#### Proposed/Revised repair cost:

| Parts                    |  |
|--------------------------|--|
| "Check items (Estimated) |  |
| Labour                   |  |
| Total                    |  |
| Lump Sum (Estimated)     |  |
|                          |  |
| 27 1 01 0 :              |  |

# Number of days of repair 3 days (est)

#### Remarks:

Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of \$2,000.00-\$3,000.00