

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 09 Mar 2022

**Preliminary Advice**

Insured Vehicle No	:	SLL2466X		
TP Vehicle No	:	SMY621Y	Accident Date	: 20/02/2022
Make	:	BMW 520I AUTO ABS AIRBAG	Assignment Date	: 07/03/2022
Date of Inspection	:	08/03/2022	Est. Duration of Repair	: 2
Inspection At	:	TRANS-CAB AUTO SERVICES PTE LTD NO 2 ANG MO KIO STREET 63 SINGAPORE 569111		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 11,173.45
Revised Amount	:	S\$ 1,405.08
Check Items (Estimated)	:	S\$ 249.53
Total	:	S\$ 1,654.61
Lump Sum Repair		:

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Survey on WP