

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS/SMO22002117/Uqy3e2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	J	Date:	26/04/2022	
			(Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XD 3427C	Veh. Inspected		SLU 2526J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD2200817/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		07/03/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC (A)	c.c		1799	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JHMFD16309S202587	Colour		GREY	
	Odometer	189464 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	MICHELIN		6 mm	
	L/H Front Tyre	205/55 R16	MICHELIN		6 mm	
	R/H Rear Tyre	205/55 R16	MICHELIN		6 mm	
	L/H Rear Tyre	205/55 R16	MICHELIN		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	04/03/2022	Inspection Date)	08/03/2022	
	Survey held at					
	Repairer					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 24 Working Days				