



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

M2053REH104546879

SLB9862S TOYOTA COROLLA ALTIS 1.6

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper <i>Rehnd</i>	\$ <del>650.00</del>
2	1	Rear bumper side retainer <i>neu</i>	\$ 95.60 ✓
3	1	Rear bumper reflector <i>neu</i>	\$ 95.60 +
4	1	Rear taillight assy	\$ 569.90 +
5	1	Rear fender light <i>neu</i>	\$ 750.90 *
6	1	Exhaust	\$ 950.00 +
			<hr/>
			\$ 3,112.00
Less <u>20%</u> 25%			\$ 622.40
			<hr/>
			\$ 2,489.60

540.20

Rear Bumper Reinforcement 398.70 x.  
N/A neu

635.80  
476.85



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLB9862S TOYOTA COROLLA ALTIS 1.6

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	6	Rear bumper lower grille clips <i>neu</i>	\$ <del>50.00</del> 30
2	8	Rear light side clips	\$ 55.00 +
3	10	Rear fender inner trim clips <i>neu</i>	\$ 50.00 +
4	10	Rear end panel inner board clips	\$ 50.00 +
5	1	Sensor <i>neu</i>	\$ 250.00 +
			<hr/>
			\$ 455.00

30

Total parts

\$ 2,944.60



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

SLB9862S TOYOTA COROLLA ALTIS 1.6

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace rear damaged parts.	\$ 700.00 <i>200</i>
2	To putty and spray painting rear portion.	\$ 800.00 <i>200</i>
3	To apply anti rust proofing to rear left affected area	\$ 120.00 <i>x</i>
4	To check wiring and focus rear headlamp.	\$ 50.00 <i>x</i>
5	To remove and install rear <del>undercarriage parts</del> <i>reverse sensor</i>	\$ <del>250.00</del> <i>50</i> 450
6	To balance front right wheel. <i>3mm</i>	\$ 60.00 <i>x</i>
7	To conduct wheel alignment.	\$ 120.00 <i>x</i>
8	To remove and install rear exhaust system <i>rpm</i>	\$ 300.00 <i>x</i>
<b>Total labour :</b>		<b>\$ 2,400.00</b>

<b>Total Parts:</b>	<b>\$ 5,568.00</b>
<b>Total Labour</b>	<b>\$ 2,300.00</b>
<b>Sub-Total</b>	<b>\$ 7,868.00</b>

01/02/23 have check with Adrian 3 ~~2~~ days.

Adrian Lij  
w/s 30/03/22.

96893735

Adrian Lij

total: 95685

A/S: 750