



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22002170/Kqy3n2 Date: 01/04/2022 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBG 8370T	Veh. Inspected	SML 8671T
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200826/GPL	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	08/03/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA FREED (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GB71087044	Colour	METALLIC RED
	Odometer	194794 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 ZR17	TOURADOR	8 mm
	L/H Front Tyre	215/45 ZR17	TOURADOR	8 mm
	R/H Rear Tyre	215/45 ZR17	TOURADOR	6 mm
	L/H Rear Tyre	215/45 ZR17	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/03/2022	Inspection Date	08/03/2022
	Survey held at	BLK 5038 AMK INDUSTRIAL PARK 2 #01-405 (S) 569541		
	Repairer	MASSIVE TRADING & AUTO		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	