

# Estimate

08/03/2022

**MS FIRST CAPITAL INSURANCE LIMITED**  
36 Robinson Road  
#16-01 City House  
Singapore 068877.

Attention :- XA026

Page # :- 1

Veh # :- SMM5118P

Veh Model :- SUZUKI SWIFT 1.0T GLX AT

Estimate# :- CK422985

Claim # :-

ACC. Date :- 01/03/22

Terms :- C.O.D Days

Remarks :-

**Main Office:**  
Mova Building  
No. 22, Jalan Kilang,  
Singapore 159419  
Tel : (65) 6476 3333  
Fax : (65) 6271 5891  
www.mova.com.sg

**Workshop Dept:**  
Block 1008,  
Bukit Merah Lane 3,  
#01-04/06/08/94  
Singapore 159722  
Tel : (65) 6272 3892  
Fax : (65) 6270 8314  
Co. Reg. 198904033G  
GST Reg. M2-0088864-2

| No.                                                                                                              | Description                  | Qty   | U.Price | Amounts S\$ |
|------------------------------------------------------------------------------------------------------------------|------------------------------|-------|---------|-------------|
| <b>LIST ITEMS :</b>                                                                                              |                              |       |         |             |
| 1.                                                                                                               | TAIL LAMP RH                 | 1 PC  | 700.00  | 700.00      |
| 2.                                                                                                               | TAILGATE EMBLEM              | 1 PC  | 50.00   | 50.00       |
| 3.                                                                                                               | TAILGATE "SUZUKI" LOGO       | 1 PC  | 52.00   | 52.00       |
| 4.                                                                                                               | TAILGATE "SWIFT" LOGO        | 1 PC  | 52.00   | 52.00       |
| 5.                                                                                                               | REAR BUMPER                  | 1 PC  | 800.00  | 800.00      |
| 6.                                                                                                               | REAR BUMPER SIDE RETAINER RH | 1 PC  | 25.00   | 25.00       |
| 7.                                                                                                               | REAR BUMPER CLIP             | 10 PC | 5.50    | 55.00       |
| 8.                                                                                                               | TAILGATE (REPAIR)            | 1 PC  |         |             |
| LIST TOTAL S\$                                                                                                   |                              |       |         | 1,734.00    |
| 15% DISCOUNT S\$                                                                                                 |                              |       |         | -260.10     |
|                                                                                                                  |                              |       |         | 1,473.90    |
| <b>LABOUR :</b>                                                                                                  |                              |       |         |             |
| TO REPAIR & STRAIGHTEN REAR END PANEL AND TAILGATE. TO REMOVE & REPLACE DAMAGED PARTS AND REALIGN ALL CONNECTION |                              |       |         | 500.00      |
| TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS                                                                        |                              |       |         | 600.00      |
| LABOUR TOTAL S\$                                                                                                 |                              |       |         | 1,100.00    |

E. & O.E

NON-TAX AMOUNT S  
AMOUNT S\$ 2,573.90  
GST @ 7 % 180.17  
AMOUNT DUE S\$ 2,754.07

Customer's Signature/Co. Stamp

MOVA AUTOMOTIVE PTE LTD