



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMZ676J HYUNDAI AD AVANTE 1.6 GLS (A)

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Front bumper			500.00		
2	Front bumper side retainer LH/RH @ 2*\$20			40.00		
1	Center grille with logo badge			550.00		
1	Headlamp RH			1,199.00		
1	Rear Bumper			500.00		
2	Rear bumper side retainer LH/RH @ 2*\$30			60.00		
1	Rear bumper lower garnish			355.00		
1	Boot lid			1,783.00		
1	Boot lid lock			120.00		
2	Boot lid both hinge LH/RH @ 2*\$60			120.00		
1	Boot lid logo badge			200.00		
1	Boot lid emblem 'Avante'			35.00		
1	Rear bumper reflector lamp RH			202.00		
1	Rear reinforcement			295.00		
1	End panel			455.00		
		Part Items Total:		6,414.00		
			5%	641.40		
				7,055.40		
	<u>SPECIAL NETT ITEMS</u>					
1	Rear reverse sensor			200.00		
1	Front bumper clips			35.00		
1	Center grille clips			30.00		
1	Rear bumper clips			35.00		
1	Rear bumper lower skirt with diffuser			900.00		
1	Front car plate with holder			35.00		
1	Rear car plate with holder			35.00		
1	End panel sealant			50.00		
		SN Items Total:		1,320.00		
		Total Parts		8,375.40		



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)


Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMZ676J HYUNDAI AD AVANTE 1.6 GLS (A)

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	
3	To perform anti-rust treatment on affected areas	60.00	
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	
5	To remove and replace rear reverse sensor	60.00	
	Labour Total :	2380.00	
	TOTAL (PARTS & LABOUR):	10755.40	



Page No. 3

QTY	DESCRIPTION (SUPPLEMENTARY)	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
			5%	0.00		
				0.00		
				0.00		
	<u>SPECIAL NETT ITEMS</u>					
	<u>LABOUR</u>					
		Total Parts	0.00			