



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg  
(199806235M)

Vehicle No. SMZ676J HYUNDAI AD AVANTE 1.6 GLS (A)

Page No. 1 of 3

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Front bumper X R		500.00	
2	Front bumper side retainer LH/RH @ 2*\$20	X nn	40.00	
1	Center grille with logo badge / # BR		550.00	/
1	Headlamp RH / CUT		1,199.00	/
1	Rear Bumper / BR		500.00	/
2	Rear bumper side retainer LH/RH @ 2*\$30	/ BR	60.00	/
1	Rear bumper lower garnish / BR		355.00	/
1	Boot lid / 01		1,783.00	/
1	Boot lid lock / BT		120.00	/
2	Boot lid both hinge LH/RH @ 2*\$60 X nn		120.00	
1	Boot lid logo badge / MC		200.00	60-
1	Boot lid emblem 'Avante' / MC		35.00	/
1	Rear bumper reflector lamp RH ? X nn		202.00	
1	Rear reinforcement / BR		295.00	/
1	End panel ? / DD		455.00	/
1	Car plate base Garnish / BR		25.00	/
1	Headlamp RH X nn		1,199.00	
Refer to next Page - 1 of 3				
Part Items Total:			7,638.00	
			5%	
			763.80	
			8,401.80	

5437  
-20%  
4349.60

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<b>SPECIAL NETT ITEMS</b>				
1	Rear reverse sensor ✓ <i>Shkl</i>		200.00 ✓	
1	Front bumper clips ✓ <i>MC</i>		<i>30</i> - 35.00 ✓	
1	Center grille clips ✓ <i>MC</i>		<i>20</i> - 30.00 ✓	
1	Rear bumper clips ✓ <i>MC</i>		<i>30</i> - 35.00 ✓	
1	Rear bumper lower skirt with diffuser ✓ <i>MC</i>	<i>cut</i>	<i>300</i> - 900.00 ✓	
1	Front car plate with holder ✓ <i>BR</i>		35.00 ✓	
1	Rear car plate with holder ✓ <i>BR</i>		35.00 ✓	
1	End panel sealant ? ✓ <i>MC</i>		<i>30</i> - 50.00 ✓	
1	Front bumper sticker ✓ <i>MC</i>		<i>80</i> - 100.00 ✓	
1	Rear bumper sticker ✓ <i>MC</i>		<i>80</i> - 300.00 ✓	
1	Car Plate sticker <u>Front/Rear</u> @2*\$50 ✓ <i>MC</i>		<i>60</i> - 100.00 ✓	
SN Items Total:			1,820.00	
Total Parts			10,221.80	

900

Refer to next Page - 2 of 3



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SMZ676J HYUNDAI AD AVANTE 1.6 GLS (A)

Page No. 3

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<b>LABOUR</b>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	<del>800</del> 1000 ✓
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	800 -
3	To perform anti-rust treatment on affected areas	60.00	30 -
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30 -
5	To remove and replace rear reverse sensor	60.00	30 -
6	To replace and focus headlamp RH	30.00 ✓	
Labour Total :		2410.00	
TOTAL (PARTS & LABOUR):		12631.80	1920

Stevie (LKK)

9/3/22, 12.00

WL ML = 7169.60

LIS LIS-5735.68

My ML sy = 5750  
6 ds

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Initiated by Repairer