

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0161/2022/JT
DATE : 4-Mar-22
WIP : 14539

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/3/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days exclude 1 Sunday

Johnny Boo 27 Apr 22

OWNER'S NAME : MR MOHAMMAD FAIZAL DE SILVA
ADDRESS : 205 LOYANG BESAR
#05-09
SINGAPORE 509456
TELEPHONE : HP +65 90093682
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900115802-02
VEHICLE NO : **SMM 6742 E**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 9/7/2019
ENGINE NO : CHZ C25993
CHASSIS NO : WAUZZZ8V7K1012853
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Feb-22
PLACE OF ACCIDENT : SLE NEAR UPPER THOMSON ROAD EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 6742 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW LHS FRONT WHEEL LOWER ARM.	S/N \$	280.00	
2	TO REMOVE AND REINSTALL REAR WHEEL SUSPENSION ASSY TO FACILITATE RENEWAL OF REAR SUBFRAME.	S/N \$	2,400.00	
3	TO REMOVE AND RENEW RHS FRONT RIM WITH TYRE AND RHS REAR RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. <i>(Both rims replaced)</i>	S/N \$	560.00	\$ 560.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 3,432.00	\$ 752.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 6742 E**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	ALUMINIUM RIM	2	\$ 2,606.00	\$	2,084.80
2	TRACK CONTROL ARM	1	\$ 393.00		
3	REAR AXLE BEAM	1	\$ 2,250.00		
4	GAS SHOCK ABSORBER	1	\$ 270.00		
5	RUBBER VALVE	4	\$ 15.00		
6	RHS FRONT TYRE	S/N	TBC	\$	270.00
7	RHS REAR TYRE	S/N	TBC	\$	270.00
8	SUNDRIES		\$ 400.00		
TOTAL SPARE PARTS		:	\$ 5,934.00	\$	2,624.80
TOTAL LABOUR CHARGES		:	\$ 3,432.00	\$	752.00
GRAND TOTAL		:	\$ 9,366.00	\$	3,376.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-19/04/22



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT