

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 18 Mar 2022

Preliminary Advice

Vehicle No	: SNA7786Z	Accident Date	: 04/03/2022
Make	: AUDI A6	Policy No.	: 7210054291
Assignment Date	: 09/03/2022	Excess	: S\$250.00
Date of Inspection	: 08/03/2022	Est. Duration of Repair	: 14
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 58,007.00
Revised Amount	:S\$ 27,860.00
Check Items (Estimated)	:S\$ 5,027.00
Total	:S\$ 32,887.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 228,000.00
COE / PARF Rebate	:S\$ 93,325.00
Salvage Value	:S\$

Margin for Repair

:S\$ 134,675.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE SOME CHECK ITEMS.