



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details			Account No.		Customer Details		
AXA Insurance Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept			S1000001 / ICASA1		Mr Gursant Singh Dhothar 68A Eng Kong Place Singapore 599182 Mobile: 84255657		
			Document No. 38066275				
			Document Date 18/08/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	TGN166R	SDTMK S4	15/04/2019	SMK5363H	45707	13623	72/UL/SMK5363H
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFGX3GS100420163		2TRA616605	60	Thomas Pang W T	02/03/2022	11.34	18/08/2022 16.04
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:GA565042 ACC DATE:01.03.2022 TOW IN:01.03.2022 EXCESS:\$500 DATE-IN:02.03.2022 DATE SURVEY:02.03.2022 NO OF REPAIR DAYS:10 WORKING DAYS BY:AXA-SHAWN AUTHORIZED ON:02.03.2022				30.00	
2	L	BP-LPO SUPPLY SOLAR FILM	0741			230.00	
3	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			180.00	
4	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION	0619			366.36	
5	Z	BP-SUNDRY TOWING FEE- \$128.40				180.00	
6	S	BP-SUBLET TO CONDUCT FULL WHEEL ALIGNMENT	0742			144.00	
7	S	BP-SUBLET REPLACE RIM AND WHEEL BALANCING	0239			720.00	
8	S	BP-SUBLET REPLACE REAR AC CON SYSTEM AND REGAS	0742			-500.00	
9	V	EXC Excess element of insurance repair to be paidby the insured party	8888			100.00	
10	S	BP-SUBLET SUPPLY SEALANT	0742			180.00	
11	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR	0742			122.40	
12	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST	0742				
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
					Others		Amount Due

Company Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details		Account No.	Customer Details				
AXA Insurance Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept		S1000001 / ICASA1	Mr Gursant Singh Dhothar 68A Eng Kong Place Singapore 599182 Mobile: 84255657				
		Document No. 38066275					
		Document Date 18/08/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	TGN166R	SDTMK S4	15/04/2019	SMK5363H	45707	13623	72/UL/SMK5363H
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFGX3GS100420163		2TRA616605	60	Thomas Pang W T	02/03/2022 11.34		18/08/2022 16.04
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	S	BP-SUBLET REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR	0742			360.00	
14	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	0742			720.00	
15	S	BP-SUBLET REPLACE RH REAR QUARTER GLASS	0742			282.00	
16	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	0742			2880.00	
17	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS	0742			2360.00	
18	1	S52159-0K952 COVER, RR BUMPER, L <i>CRA</i>	1.00	547.10	15.00	465.03	
19	2	S52169-0K200 COVER, RR BUMPER, LW <i>Def</i>	1.00	202.00	15.00	171.70	
20	3	S75392-0K010 RETAINER, OUTSIDE MO <i>Nec</i>	10.00	4.20	15.00	35.70	
21	4	S52161-0K040 PIECE, RR BUMPER <i>Nec</i>	10.00	4.30	15.00	36.50	
22	5	S52706-0K040 MOULDING SUB-ASSY, R <i>>Grazed</i>	1.00	156.20	15.00	132.77	
23	6	S52707-0K040 MOULDING SUB-ASSY, R <i>>Grazed</i>	1.00	156.20	15.00	132.77	
24	7	S76625-0K370 MUDGUARD, RR BODY, R <i>CRA</i>	1.00	109.20	15.00	92.82	
25	8	S61601-KK010 PANEL SUB-ASSY, QUAR <i>cut</i>	1.00	1358.90	15.00	1155.06	
26	9	S62710-0K400 WINDOW ASSY@ <i>Nec</i>	1.00	435.80	15.00	370.43	
27	0	S62930-0K160 DUCT ASSY, QUARTER V <i>Damaged</i>	1.00	112.90	15.00	95.96	
28	1	S67003-KK030 PANEL ASSY,RR DR RH <i>Dent</i>	1.00	1597.40	15.00	1357.79	
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary			Total	
		Please acknowledge receipt of vehicle	Parts			Less	
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others			Amount Due	

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

TAX INVOICE

Account Details	Account No.	Customer Details
AXA Insurance Pte Ltd 8 Shenton Way #27-01 Singapore 068811 Attn: Motor Claims Dept	S1000001 / ICASA1	Mr Gursant Singh Dhothar 68A Eng Kong Place Singapore 599182 Mobile: 84255657
	Document No. 38066275	
	Document Date 18/08/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	TGN166R	SDTMK S4	15/04/2019	SMK5363H	45707	13623	72/UL/SMK5363H
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFGX3GS100420163	2TRA616605	60	Thomas Pang W T	02/03/2022	11.34	18/08/2022	16.04

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	2	S75923-OK130 TAPE, BLACK OUT, NO. >Nec	1.00	50.90	15.00	43.26
30	3	S75925-OK050 TAPE, BLACK OUT, NO. >Nec	1.00	46.20	15.00	39.27
31	4	T90975-02086 EMBLEM,SYMBOL Nec	1.00	72.20	15.00	61.37
32	5	S75441-OK130 PLATE, BACK DOOR NAM Nec	1.00	48.30	15.00	41.05
33	6	S75605-OK050 MOULDING SUB-ASSY, Q Def	1.00	166.20	15.00	141.27
34	7	S81480-OK050 LAMP ASSY, RR@ Missing	1.00	461.10	15.00	391.93
35	8	S89341-OK011 J0 SENSOR, ULTRASONIC, Shorted	2.00	392.80	15.00	667.76
36	9	T21000-20 SIKI 210002-0 TACK GO! (BLACK) SG	1.00	108.00	15.00	91.80
37	0	T21000-22 SIKI 210002-2 G+P 207 ADHESIVE PRIMER >nec	1.00	200.00	15.00	170.00
38	1	T08826-08115 PANEL BONDING AD Nec	1.00	267.20	15.00	227.12
39	2	S42611-OKL10 WHEEL, DISC Damaged	1.00	2648.10	15.00	2250.88
40	3	S88500-OK281 AIR CONDITIONER & AC Damaged.	1.00	1593.70	15.00	1354.64
41	4	S52562-OK050 RETAINER, RR Nec	1.00	52.40	15.00	44.54
42	5	S66251-OK070 SUPPORT, MUDGUARD RR >CRA	1.00	129.90	15.00	110.41
43	6	S66251-OK080 SUPPORT, MUDGUARD RR >CRA	1.00	88.50	15.00	75.22
44	7	S52575-OK130 RETAINER, RR BUMPER Nec	1.00	113.50	15.00	96.47
Fair & Reasonable 10 repair days.						

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	18,208.28
	Please acknowledge receipt of vehicle	Parts 9,853.52	GST 7.00%	1,274.58
		Labour 30.00	Less	0.00
		Sublet 8,824.76		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	19,482.86

Company Copy