YQ 5158K

i		SUPP (PARTS)	<u> </u>	LABOU		S/I				PARTS
İ	\$0.00		\$20.00		\$480.00		\$0.00	\$0.00	\$1,005.20	
İ	\$0.00		\$40.00		\$50.00		\$0.00	\$0.00	\$342.90	
İ	\$0.00		\$100.00		\$0.00		\$0.00	\$0.00	\$50.00	
İ	\$0.00		\$60.00		\$0.00		\$0.00	\$0.00	\$350.90	
İ	\$0.00		\$600.00		\$0.00		\$0.00	\$0.00	\$1,014.60	
İ	\$0.00		\$900.00		\$0.00		\$0.00	\$0.00	\$647.80	
İ	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$1,915.00	
İ	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$68.00	
İ	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$305.00	
İ	0%		\$0.00		\$0.00		\$0.00	\$0.00	\$1,550.00	
1	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	
1		SUPP (SN)	\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$0.00		\$0.00)	\$0.00	\$0.00	\$0.00	
1	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$0.00	
İ	<u>\$0.00</u>		\$1,720.00		\$0.00		\$0.00	\$0.00	\$0.00	
1					\$0.00)	\$0.00	\$0.00	\$0.00	
İ		SUPP(LABOUR)			\$0.00		\$0.00	\$0.00	\$0.00	
İ	\$0.00			TOTAL	\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$6,524.46		\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$530.00		\$0.00		\$0.00	\$0.00	\$0.00	
1	\$0.00		\$1,720.00		\$0.00		\$0.00	\$0.00	\$0.00	
•	\$0.00	TOTAL SUPP	\$0.00	SUPP	\$530.00		\$0.00	\$0.00	\$0.00	
	HINO XZU710R - 4009cc	MAKE / MODEL	\$8,774.46	P/P	<u>'</u>		\$0.00	\$0.00	\$0.00	
	\$80,000.00	MARKET VALUE				_			\$0.00	
	\$19,273.00	LTA REBATE	80%)	\$0.00	\$0.00	\$0.00	
	\$60,727.00	NETT VALUE	\$7,019.57)	\$7,249.40	\$0.00	\$0.00	
68%	\$14,605.00	RED	\$7,000.00	L/S				\$0.00	\$0.00	
	\$21,605.00	TOTAL TP EST)	\$7,249.40	\$0.00	\$0.00	
	<u>4</u>	REPAIR DAYS				6	90%	\$0.00	\$0.00	
		<u>REMARKS</u>				<u>5</u>	<u>\$6,524.46</u>	\$0.00	\$0.00	