

cecilia

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorized  
her  
9/3/22  
2/s \$7000/  
4 days.

VEHICLE No: YQ 5158K

1PC	FRONT BUMPER	Dis 1005-20	\$1,615.00	/
1PC	FRONT BUMPER BRACKET N/S	Bent 342.80	\$520.00	/
1SET	FRONT BUMPER CLIPS	all	\$50.00	/
1PC	FRONT BUMPER FOG LAMP N/S	one 350.90	\$485.00	/
1PC	HEADLAMP N/S	one 1014.60	\$1,650.00	/
1PC	FRONT CORNER PANEL GARNISH N/S	one 647.80	\$745.00	/
1PC	FRONT MIRROR BRACKET ASSY N/S	R	\$990.00	X
1PC	FRONT MIRROR N/S	11	\$295.00	X
1PC	FRONT PANEL	R	\$2,450.00	X
1PC	FRONT PANEL STICKER	11	\$100.00	X
1PC	FRONT PANEL '300' EMBLEM	11	\$150.00	X
1PC	FRONT PANEL 'HINO' EMBLEM	11	\$128.00	X
1PC	FRONT DOOR N/S	22/Bent 1915.00	\$3,205.00	/
1PC	FRONT DOOR OUTER PILLAR N/S	R	\$2,115.00	X
1PC	FRONT DOOR '616' STICKER N/S	all 68.00	\$102.00	/
1PC	FRONT DOOR INNER LOCK N/S	11	\$450.00	X
1PC	FRONT DOOR HINGE N/S	82	\$105.00	X
1PC	FRONT STEP GARNISH N/S	cut 305.00 (102)	\$650.00	/
1PC	AIR CON CONDENSER	Bent/TW 1550.00	\$1,550.00	/
			\$17,355.00	

S.NETT

1SET	FRONT DOOR CORPORATE STICKER N/S	all	\$700.00	480 S/N
1SET	FRONT DOOR 'ROC' STICKER N/S	all	\$50.00	/

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$120.00	40
TO REFILL AIR CON GAS	\$120.00	100
TO TRANSFER FRONT DOOR MECHANISM	\$100.00	60
TO RESET & REPROGRAMME SYSTEM	\$180.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,250.00	600
TO PUTTY & SPRAY PAINTING	\$1,680.00	900
TOTAL	\$21,605.00	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7249.4

103

9-6524-46

S.N- 530

1720

8774-46