



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0182/2022/ZK  
**DATE** : 9-Mar-22  
**WIP** : 15082

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 15/03/2022**

**YOUR INSURED VEH NO : SGG 7100 D**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS SERENE WAH YU MEI (SERENE HUA YUMEI)  
**ADDRESS** : 6 TAI THONG CRESENT  
#07-04  
SINGAPORE 347840  
**TELEPHONE** : HP +65 9239 8145  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 7210010730  
**VEHICLE NO** : **SMX 9079 J**  
**MODEL CODE** : AUDI Q3 SPORTBACK 1.4 TFSI S  
**MODEL YEAR** : 4/2/2021  
**ENGINE NO** : CZD C25602  
**CHASSIS NO** : WAUZZZF35M1068018  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 5-Mar-22  
**PLACE OF ACCIDENT** : 6 TAI TAONG CRESCENT CARPARK



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 9079 J**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$	480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MOUDULE	S/N \$	400.00	
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF RHS FRONT DOOR.	S/N \$	280.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$	2,400.00	
5	TO RESPRAY FRONT BUMPER , FRONT BUMPER LOWER SPOILER , RHS FRONT FENDER , RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	\$	4,500.00	
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 8,252.00</b>	

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9079 J**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,423.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 433.00	
3	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	
4	FRONT BUMPER SPOLER	1	\$ 850.00	
5	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00	
6	FRONT BUMPER TRIM	1	\$ 182.00	
7	FRONT PARKING AID SENSOR SUPPORT - RH	1	\$ 43.00	
8	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00	
9	FRONT FENDER - RH	1	\$ 1,445.00	
10	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	
11	FRONT FENDER BRACE - RH	1	\$ 98.00	
12	FRONT FENDER BRACKET - RH	1	\$ 39.00	
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00	
14	FRONT FENDER INSULATION	1	\$ 48.00	
15	FRONT WHEEL HOUSING LINER - RH	1	\$ 260.00	
16	FRONT WHEEL HOUSING LINER COVER	1	\$ 18.00	
17	WHEEL HOUSING LINER ATTACHEMENT PARTS	1	\$ 105.00	
18	HEADLIGHT MOUNTING - RH	1	\$ 132.00	
19	HEADLIGHT - RH	1	\$ 5,952.00	
20	HEADLIGHT LIFT CYLINDER - RH	1	\$ 231.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 11,788.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:       REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                   SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9079 J**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	HEADLIGHT HOSE	1	\$ 92.00	
22	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 1,132.00	
23	SUNDIRES		\$ 300.00	
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 13,312.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 8,252.00</b>	
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 21,564.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
                  SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT