

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0182/2022/ZK
DATE : 9-Mar-22
WIP : 15082

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 15/03/2022
YOUR INSURED VEH NO : SGG 7100 D

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS SERENE WAH YU MEI (SERENE HUA YUMEI)
ADDRESS : 6 TAI THONG CRESENT
#07-04
SINGAPORE 347840
TELEPHONE : HP +65 9239 8145
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7210010730
VEHICLE NO : **SMX 9079 J**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFSI S
MODEL YEAR : 4/2/2021
ENGINE NO : CZD C25602
CHASSIS NO : WAUZZZF35M1068018
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Mar-22
PLACE OF ACCIDENT : 6 TAI TAONG CRESCENT CARPARK

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Xiao Tong.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 90791

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 400.00	x. 250 <i>sls</i> ✓
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF RHS FRONT DOOR.	S/N \$ 280.00	✓ ✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, <u>RHS FRONT FENDER</u> AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$ 2,400.00	500 + 500 <i>sls</i> ✓
	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, RHS FRONT FENDER, RHS FRONT DOOR AND BOTH FRONT WHEEL ARCH TRIMS	\$ 4,500.00	2050 3x550 = 1650 <i>sls</i> ✓ Wheel Arch x 2 = 400
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 8,252.00	

Adrian Lj
sls Resurveyed.

Car in 4/4/22 wip : 15082

PREMIUM AUTOMOBILES

kiam /



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ALG - Admin
- 5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9079

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defect</i>	1	\$ 1,423.00	✓ 1,138.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 433.00	+
3	FRONT BUMPER CLOSING ELEMENT <i>X NN</i>	1	\$ 212.00	X
4	FRONT BUMPER SPOILER <i>new</i>	1	\$ 850.00	✓
5	FRONT BUMPER AIR GUIDE GRILLE - RH <i>new</i>	1	\$ 171.00	+
6	FRONT BUMPER TRIM <i>new</i>	1	\$ 182.00	+
7	FRONT PARKING AID SENSOR SUPPORT - RH <i>new</i>	1	\$ 43.00	✓
8	FRONT BUMPER GUIDE SECTION - RH <i>X NN</i>	1	\$ 43.00	X
9	FRONT FENDER - RH <i>Buckled</i>	1	\$ 1,445.00	✓ <i>lls</i> 1,156.00
10	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 66.00	✓
11	FRONT FENDER BRACE - RH <i>Best</i>	1	\$ 98.00	✓ <i>lls</i> 77.68
12	FRONT FENDER BRACKET - RH <i>Best</i>	1	\$ 39.00	✓ <i>lls</i> 30.48
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00	✓
14	FRONT FENDER INSULATION	1	\$ 49.00	✓
15	FRONT WHEEL HOUSING LINER - RH <i>new</i>	1	\$ 260.00	✓
16	FRONT WHEEL HOUSING LINER COVER	1	\$ 18.00	✓
17	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 105.00	✓
18	HEADLIGHT MOUNTING - RH <i>new</i>	1	\$ 132.00	✓
19	HEADLIGHT - RH <i>cracked</i>	1	\$ 5,952.00	✓ <i>lls</i> 4,761.60
20	HEADLIGHT LIFT CYLINDER - RH <i>new</i>	1	\$ 231.00	✓
SUB TOTAL SPARE PARTS		:	\$ 11,788.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 9079 J

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HEADLIGHT HOSE <i>nm</i>	1	\$ 92.00	<i>+</i>
22	FRONT WHEEL ARCH COVER - LH / RH <i>nm</i>	2	\$ 1,132.00	<i>✓</i>
23	SUNDIRES X NN ?		\$ 300.00	X
TOTAL SPARE PARTS		:	\$ 13,312.00	
TOTAL LABOUR CHARGES		:	\$ 8,252.00	
GRAND TOTAL		:	\$ 21,564.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lg*
SURVEYED DATE : *15/03/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *xre Authorised, 05 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: