

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 2022 22004161/FQ Date: 25<sup>th</sup> May 2022

Our Ref: CS6/AIS22002211/Kty3e2

## M/s Allianz Insurance Singapore Pte Ltd

79 Robinson Road #09-01 Singapore 068897

Dear Sir / Madam,

## DESKTOP SURVEY OF ACCIDENT VEHICLE SLJ 1541D ACCIDENT ON 08/03/2022

We thank you for your instruction on 09/03/2022.

The following vehicle information was recorded:

Registration Number : SLJ 1541D

Make & Model : Honda HRV 1.5 LX CVT Chassis Number : JHMRU1830GX201388

Year of Registration : 2016 Engine Capacity : 1496 cc

- 1. The vehicle sustained damages at the front portion. (Details see photographs enclosed)
- 2. We recommend that the repairs of the entire damage require about <u>6 (Six)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.