

Our Job Ref No : 305505440
Date : 19/02/22

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508909
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHC8884C

Date of Accident : 16.02.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: CHINA TAIPING --- GBL1610X
- The finalized amount shall be:
 - Spare Parts after List discount \$628.67
 - Labour Charges (include advertisement stickers etc,if any) \$630.00
 - Total for Part-By-Part Repair Cost \$1,258.67
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
- Estimated normal period for repairs: 2 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : LIM T S

Tel : 62148398

Fax : 65468156

Signature : 

Name : THEVAN

Date : 14/3/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-Thevan

DATE: 17-Feb-22

MODEL: Toyota Prius

VEHICLE NO.: SHC8884C

INSURANCE: CHINA TAIPING (CP/P)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$458.60 X
	Rear Bumper Re-Inforcement	1		\$318.80 N. X Svc
	Rear Bumper Lower Cover-Black	1		\$552.60 / Scr
	Rear Bumper Tow Cover	1		\$82.70 / DES
	Rear Bumper Clips	10	\$2.20	\$22.00 / MC
	SUB TOTAL			\$1,434.70
	LESS 25%			\$358.68
	DISCOUNTED TOTAL			\$1,076.03
	Reverse Sensor	1		\$135.70 / Car
	Rear Bumper Mat	1		\$50.00 X Svc
	NETT TOTAL			\$185.70
	TOTAL SPARE PARTS			\$1,261.73
	Labour Charge			
	Panel Beating			\$400.00 350
	Spray Painting Charge			\$300.00 250
	Remove/Refix Reverse Sensor			\$120.00 30
	TOTAL LABOUR			\$820.00
	ESTIMATE TOTAL			\$2,081.73

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan 82235769

17/2/22 1715

P/P bfr paint photo

2 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 18.02.2022
Time: 14:58:02
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305505440
REGN NO : SHC8884C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 15.04.2020
DATE/TIME IN : 17.02.2022 12:10
ACCIDENT DATE : 16.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2713-G	REAR BUMPER LOWER COVER	1	552.60	25.00	414.45
0002 04-01-0302-2715-G	REAR BUMPER TOW COVER	1	82.70	25.00	62.02
0003 04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00	25.00	16.50
0004 09-01-0302-2005-A	REVERSE SENSOR	1	135.70	2.50	135.70


SUB-TOTAL : 628.67

JOB NATURE

0000 PB	PANEL BEATING-SHC8884C	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	R/I REVERSE SENSORS	30.00

SUB-TOTAL : 630.00

TOTAL : 1,258.67


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :
AUTHORISED : YES / NO