

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Mar 2022 00:32	CIm Veh Model Changed		[] Merimen Administrator
2	08 Mar 2022 00:32	CIm Created	Reg No: SML487L. Policy No: 1900093882-01. Acct Date: 2022/03/06. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R22370003	[I] Merimen Administrator
3	08 Mar 2022 10:17	CIm Registration Modified	Acct Time:18:20:00->18:00:00. Pol No:1900093882-01->1900093882. Init.Est.->5,000 - 6,000.	[I] Subramaniam, Divyashni
4	08 Mar 2022 10:17	CIm Veh Model Changed	(204214) AUDI Q5 2.0 (A).	[I] Subramaniam, Divyashni
5	10 Mar 2022 12:03	CIm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
6	10 Mar 2022 12:03	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
7	10 Mar 2022 12:03	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
8	10 Mar 2022 12:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/21	[A] CELINE FONG
9	10 Mar 2022 12:03	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
10	10 Mar 2022 12:03	CIm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
11	10 Mar 2022 12:03	CIm Veh Model Changed	(204214) -> (206231) AUDI Q5 SPORT 2.0 TFSI QU S TRONIC (A).	[A] CELINE FONG
12	10 Mar 2022 12:04	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CELINE FONG
13	10 Mar 2022 15:14	CIm Registration Modified	Excess: -> 500.00. Excess Waived: -> 500.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
14	11 Mar 2022 14:20	Adj Rpt Initiated		[A] HUEY YON
15	11 Mar 2022 14:20	CIm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
16	11 Mar 2022 14:20	CIm Dtl Modified	JPJ Reg. Date: -> 2019/04/30.	[A] HUEY YON

AUDIT TRAIL			
No.	On Audit	Remarks	By
17	11 Mar 2022 14:20 Clm Details Notified		[A] HUEY YON
18	14 Mar 2022 09:02 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/21	[A] SHIAU CHAN
19	14 Mar 2022 09:03 Adj Mandate Request	Cur Req:13151.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
20	14 Mar 2022 09:49 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/21. Mandate Remarks: Vehicle may commence repair - FRONT BUMPER AIR GUIDE GRILLE-LH/RH to resurvey with CLEARER damaged photos Checked and Supplementary items to resurvey with CLEAR photos for damage and consist	[I] Lim, Kok-Chong
21	14 Mar 2022 09:49 Adj Mandate Set	Approved:11003.00:Vehicle may commence repair - FRONT BUMPER AIR GUIDE GRILLE-LH/RH to resurvey with CLEARER damaged photos Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos fo	[I] Lim, Kok-Chong
22	31 Mar 2022 12:25 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/21	[A] SHIAU CHAN
23	31 Mar 2022 12:25 Adj Mandate Request	Cur Req:13415.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL.	[A] SHIAU CHAN
24	31 Mar 2022 15:36 Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/03/21. Mandate Remarks: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen	[I] Lim, Kok-Chong
25	31 Mar 2022 15:36 Adj Mandate Set	Approved:11538.00: Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From 
Date To 
Audit Type

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2773079	11 Mar 2022 14:20:09	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SML487L		11.00