



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC22002292/Ety3e2 Date: 09/06/2022 Code: LPC2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	XD 5342A
	<b>Policy No.</b>	Z/21/VC00/112757	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	21/22/22/VC00/025406	<b>Excess (\$)</b>	2,000.00
	<b>Assign From</b>	KENNY LIM	<b>Assign Date</b>	11/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HINO FS1ELKD	<b>c.c</b>	12913
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2012
	<b>Chassis No.</b>	JHDFS1ELKXXX12130	<b>Colour</b>	WHITE
	<b>Odometer</b>	-	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	295/80 R22.5	GOODYEAR	4 mm
	<b>L/H Front Tyre</b>	295/80 R22.5	GOODYEAR	4 mm
	<b>R/H Rear Tyre</b>	295/80 R22.5	GOODYEAR	4 mm
	<b>L/H Rear Tyre</b>	295/80 R22.5	GOODYEAR	4 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	24/01/2022	<b>Inspection Date</b>	11/03/2022
	<b>Survey held at</b>	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
<b>5a. Remarks</b>				
	A)THE MARKET VALUE IS S\$40,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	