



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22002294/Rny3e2 Date: 27/07/2023 Code: FCI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SMB 5063X	
	Policy No. D-19094584MFBP	Coverage (\$)	0.00	
	Claim No. D22000550MFBP	Excess (\$)	50,000.00	
	Assign From LYNN AHMAD	Assign Date	11/03/2022	
2. Vehicle Particulars & Condition				
	Make & Model ALEXANDER DENNIS ENVIRO500	c.c	8849	
	Engine No. HIDDEN	Year of Reg.	2015	
	Chassis No. SFD76CLR5EMTL3779	Colour	MULTI COLOUR	
	Odometer -	Steering	IN ORDER	
	Brakes IN ORDER	Modification	NIL	
	General FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	305/70 R22.5	FIRENZA	8 mm
	L/H Front Tyre	305/70 R22.5	FIRENZA	8 mm
	R/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	8/8 mm
	L/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 21/02/2022	Inspection Date	11/03/2022	
	Survey held at 310 MANDAI ROAD			
	Repairer TOWER TRANSIT SINGAPORE PTE. LTD.			
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		30 Working Days	