

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	CHINA TAIPING IN	ISURANCE (S) PTE LTD	Ref	CS3/CTI21011206/Rty3e2-1	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909	Date	e: 14/04/2022	
			Cod	le: CTI	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SLK 94D	Veh. Inspected	SND 223L	
	Policy No.	DMPCSNW00166702002	Coverage (\$)	0.00	
	Claim No.	SNM21D205974/C02/TANKL	Excess (\$)	0.00	
	Assign From	TAN KAH LEONG	Assign Date	09/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	FERRARI 458 SPIDER 4.5L	c.c	4497	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	ZFF68NHC000202078	Colour	WHITE	
	Odometer	60007 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	295/35Z R20	MICHELIN	6 mm	
	L/H Front Tyre	295/35Z R20	MICHELIN	6 mm	
	R/H Rear Tyre	295/35Z R20	MICHELIN	6 mm	
	L/H Rear Tyre	295/35Z R20	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	18/10/2021	Inspection Date	14/03/2022	
	Survey held at	urvey held at 160 Sin Ming Drive #06-13 Sin Ming Autocity			
	Repairer Y2K AUDIO DESIGN				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				
	•				