

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22002319/KQY3Q2**Date:** 30/08/2022**REFERENCE**

Insured/Claimant: ISHAK BIN IBRAHIM Policy No: DMPCSNW00247882100

Date of Loss: 09/03/2022 Nature of Claim: OD Claim No: SNM22D201686/C01/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKA4415A**  
 Make & Model: CHEVROLET CRUZE, 1.6 (A) Engine No: F16D4227849KA  
 Reg. Date: 28/02/2011 (Man. Year: 2010) Chassis No: KL1JA69E9BK082284  
 Colour: Metallic Red Odometer: 76794 km  
 Engine Capacity: 1598 cc  
 Market Value/New Car Price: S\$29,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,284.00	4,387.20	1,896.80	30.18
Miscellaneous Items	140.00	140.00	0.00	0.00
Labour	2,421.48	2,341.68	79.80	3.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,845.48</b>	<b>6,868.88</b>	<b>1,976.60</b>	<b>22.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,850.00</b>		
<b>(S\$)</b>	8,845.48	6,850.00	1,995.48	22.56
<b>+ GST 7.00/7.00% (S\$)</b>	619.18	479.50	139.68	22.56
<b>Nett Amount (S\$)</b>	<b>9,464.66</b>	<b>7,329.50</b>	<b>2,135.16</b>	<b>22.56</b>

**INSPECTION**

Date of Assignment: 14/03/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)  
 Date Inspected: 14/03/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
 Blk 1019 #01-374/382, Yishun Industrial Park A  
 Singapore 768761  
 Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2022)
Parts:	143	CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKA4415A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		6,284.00 F	*5,484.00 FL
<u>Supplementary #1</u>						
2	1		*1PC AUTOMATIC TRANSMISSION (NPA)	Not Necessary	-	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					6,284.00	5,484.00
- List Item Discount on L Items 0.00/20.00% (\$)					0.00	1,096.80
Total Parts (\$)					6,284.00	4,387.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	EXTRAS	40.00	40.00
2	1	SUNDRY	100.00	100.00
<b>Sub Total (\$\$)</b>			<b>140.00</b>	<b>140.00</b>

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	1,289.40	1,209.60
2	SPRAY PAINTING	New	1,132.08	1,132.08
<b>Gross Labour Cost (\$\$)</b>			<b>2,421.48</b>	<b>2,341.68</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >