



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS3/MSG22002346/y3 Date: 14/03/2022 Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLS 554B	Veh. Inspected	BICYCLE	
Policy No.	30001622887	Coverage (\$)	0.00	
Claim No.	266291	Excess (\$)	0.00	
Assign From	CHRISTINA WONG	Assign Date	14/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2021	Inspection Date		
Survey held at	BLK 335A YISHUN ST 31 #15-77 S761335			
Repairer	-			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				