## **Spark Car Care**

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

## Supplementary 1

Vehicle No	: <u>GBE9803R</u>	Case Owner	: PATRICK
Make & Model	: FIAT DOBLO CARGO MAXI	Year Manufacture	e : 2016/MAR - 1.6 MTJ A
Chassis No	ZFA26300006C06098	Engine No	; <u>0</u>
Sales Order	: 0	Supplier	i: <u>0</u>
Order By		Type of Claim	: OD

S/No	Part Description	QTY	Cost	List	Nett	0.01	Disposition By
1	BONNET LOCK DISTORTED	+-	Price	Price	Item	S/N	Surveyor
	BONNET LOCK DISTORTED BONNET PUB STICKER	1		\$ 122.00	NEO	0.450.00	
	0	1			NEC	\$ 150.00	
	0	+					
5	0	+					
6		+					
7		+ -					
8		_					
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.