



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CYNTHIA ONG

Ref: CS/INC22002392/Rqy3e2

Date: 08/06/2023

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 7076E	Veh. Inspected	SMR 8316M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1160711-002	Excess (\$)	0.00
Assign From	Theresa Vimala	Assign Date	15/03/2022

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN TOURAN 1.4 TSI	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WVGZZZ1TZKW072811	Colour	GREY
Odometer	60613 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	PIRELLI	6 mm
L/H Front Tyre	215/55 R17	PIRELLI	6 mm
R/H Rear Tyre	215/55 R17	PIRELLI	6 mm
L/H Rear Tyre	215/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/02/2022	Inspect Date / Time	15/03/2022 (04:43 PM)
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------