

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS/INC22002397/Ety3n2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date	04/05/2022	
	ATTN: AZHARI		Code	: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 850C	Veh. Inspected	SLN 5002X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1161753-002	Excess (\$)	0.00	
	Assign From	THERESA VIMALA	Assign Date	15/03/2022	
2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JM6BN24A8H0144820	Colour	RED	
	Odometer	86564 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
	L/H Front Tyre	205/60 R16	BRIDGESTONE	5 mm	
	R/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
	L/H Rear Tyre	205/60 R16	BRIDGESTONE	5 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
				5.0	
5.	General Information				
	Accident Date	13/02/2022	Inspect Date / Time	15/03/2022 ( 12:29 PM )	
	Survey held at	ETHOZ GROUP LTD			
		30 BUKIT BATOK CRESCENT SINGAPORE 658075			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				