

21

China (L8)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 11.03.2022

Time: 15:14:28

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305508457  
REGN NO : SHD8629T  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G2)  
DATE OF REGN : 04.12.2018  
DATE/TIME IN : 11.03.2022 11:40  
ACCIDENT DATE : 11.03.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	REMARKS
0001	04-01-0104-2256-G	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00 1,984.32 <i>bt</i>
0002	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00 19.44 <i>all</i>
0003	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00 25.04 <i>all</i>
0004	28-01-0103-0009-A	REAR BOOT LOGO CCTPL	1 N	30.00	2.00- 30.00 <i>all</i>
0005	28-01-0103-0010-A	REAR BOOT TEL NUMBER CCTP	1 N	30.00	0.20 30.00 <i>all</i>
0006	28-01-9999-2024-A	APP LOGO REAR DOOR L/R CC	1 N	40.00	0.02- 40.00 <i>all</i>
0007	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00 367.52 <i>all</i>
0008	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00 361.00 <i>all</i>
0009	04-01-0104-2288-G	BEAM-RR BUMPER	1	394.80	20.00 315.84 <i>all</i>
0010	04-01-0104-2370-G	LAMP ASSY-REAR FOG	1	201.50	20.00 161.20 <i>Xun</i>
0011	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00 32.40 <i>Xun</i>
0012	04-01-0104-2257-G	GLASS ASSY-TAIL GATE LOWE	1	384.90	20.00 307.92 <i>*Xun</i>
0013	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	2.00- 50.00 <i>all</i>

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305508457  
 REGN NO : SHD8629T  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 04.12.2018  
 DATE/TIME IN : 11.03.2022 11:4  
 ACCIDENT DATE : 11.03.2022

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT	
0014 04-01-0104-2346-G PANEL ASSY-BACK	1		532.00	20.00	425.60	Rx
0015 04-01-0101-0111-G BUMPER COVER CLIP REAR	10		22.00	20.00	17.60	net
0016 04-01-0104-1150-A PROTECTOR MAT	1 N		50.00	2.00-	50.00	net
0017 05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC	2 N		46.00	0.20	46.00	net
						4139.65
						3311.72
						SUB-TOTAL : 4,263.88
						246 Net
JOB NATURE						
Supp Rear bumper stay LH \$138.10 bt/						
Net bumper stay RH \$138.10 bt/						
0000 PB PANEL BEATING			1200.00			700
0001 SP SPRAYPAINT CHARGE			800.00			750
0002 17-01 CHECK ALL LIGHTING			50.00			30
0003 20-00 TUFF COAT ON AFFECTED PARTS.			50.00			30
0004 20-05 RENEW ADVERTISEMENT STICKER-BOOT			100.00			net

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305508457  
 REGN NO : SHD8629T  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G2)  
 DATE OF REGN : 04.12.2018  
 DATE/TIME IN : 11.03.2022 11:4  
 ACCIDENT DATE : 11.03.2022

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0005 L REMOVE/REFIX REVERSE SENSOR	50.00		30		
0006 L REMOVE/REFIX RR WINDSCREEN GLASS	120.00		✓		1760
SUB-TOTAL :					2,370.00
TOTAL :					6,633.88

MVA NAME & SIGNATURE  
 DATE :

AUTHORISED : YES / NO  
 SURVEYOR NAME & SIGNATURE  
 DATE :

3311.72  
 246  
 1760  
 -----  
 5317.72  
 1/3 \$4250 #  
 03 days  
 03 days  
 Taufiqi 97495747  
 'WP' 11/3/22 @ 330pm  
 c/s Resurvey after repair  
 Taufiqi Chandra

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: