

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS/INC22002403/Kvy3n2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	30/03/2022	
	ATTN: JARED LIU			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJE 1113G	Veh. Inspected		SJX 9750P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1164828-002	Excess (\$)		0.00	
	Assign From	THERESA VIMALA	Assign Date		15/03/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VIOS (A)	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	MR053HY9305167290	Colour		WHITE	
	Odometer	229556 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/50 R16	TOURADOR		8 mm	
	L/H Front Tyre	195/50 R16	TOURADOR		8 mm	
	R/H Rear Tyre	195/50 R16	TOURADOR		8 mm	
	L/H Rear Tyre	195/50 R16	TOURADOR		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DI	ETAILS.			3.0	
_						
5.	General Information					
	Accident Date	11/03/2022	Inspect Date /	Time	16/03/2022 ( 10:36 AM )	
	Survey held at	TSR AUTOMOTIVE PTE LTD				
		160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		4 Worki	ng Days	