



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: DAVID PHUA

Ref: CS/INC22002417/Vty3e2

Date: 18/05/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|----------------|----------------|------------|
| Insured Veh. | FBC 8866B | Veh. Inspected | FBS 4272G |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | MT/1164531-002 | Excess (\$) | 0.00 |
| Assign From | Theresa Vimala | Assign Date | 15/03/2022 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|-------------------|--------------|--------------------|
| Make & Model | HONDA CB400XA | c.c | 399 |
| Engine No. | HIDDEN | Year of Reg. | 2021 |
| Chassis No. | JH2NC5692KK000497 | Colour | BLACK |
| Odometer | - | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|------------|--------|---------|
| R/H Front Tyre | 110/80 R19 | DUNLOP | 6 mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | 110/80 R19 | DUNLOP | 6 mm |
| L/H Rear Tyre | | | mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|----------------|--|---------------------|-------------------------|
| Accident Date | 09/03/2022 | Inspect Date / Time | 15/03/2022 (05:30 PM) |
| Survey held at | KIVILE ENTERPRISE BLK 3007 #01-408 UBI ROAD 1 SINGAPORE 408701 (MOTORCYCLE ONLY) | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**