

QUOTATION FOR REPAIR :JRL2389

Qty	Description	Repairer's Estimate
1	FRONT MUDGUARD (RED) <i>cm</i>	124.00
1	RHS Z PANEL (RED) <i>cm</i>	155.00
1	HEADLIGHT <i>sun</i>	212.00
1	FRONT FOOTREST BRACKET <i>repair</i>	143.00 <i>XR</i>
1	FRONT RHS FOOTREST RUBBER <i>cut</i>	82.00
1	HANDLEBAR <i>Xnn</i>	163.00 <i>X</i>
1	LHS Z PANEL (RED) <i>cm</i>	155.00
1	RHS INNER PANEL (BLACK) <i>cm</i>	144.00
1	RHS REAR BRAKE PEDAL <i>repair</i>	108.00 <i>XR</i>
1	EXHAUST PROTECTOR <i>sun</i>	138.00
1	TOP BOX <i>Xnn</i>	185.00 <i>X</i>
1	BALANCER SET <i>Xnn</i>	85.00 <i>X</i>

Less 10%	1,694.00
Total Part :	169.40
Nett items	1,524.60

1010
102
909

Passed
Hp 9001008
3 days

Total Nett items :	0.00
Total parts :	1,524.60

45
16/03/22 @ 1430
Reby after repair

Labour Fee

FORK ALIGNMENT
FRONT RIM ALIGNMENT
CHASSIS ALIGNMENT
LABOUR FEE

~~220.00~~ 40
~~220.00~~ *Xnn*
~~500.00~~ *Xnn*
~~600.00~~ 300 } 340

Total Labour Fee:	1,540.00
Total parts and labour charges :	3,064.60
	7 DAYS

909
340
1249
202
999

4/2 - \$1,000