

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile				
	NTUC INCOME IN	SURANCE CO-OPERATIVE LTD	Ref:	CS3/INC22002418/Rvy3
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	15/03/2022
			Code:	INC
1.	Policy Particulars :- (THIRD PARTY CLAIM)			
	Insured Veh.	YN 5536T	Veh. Inspected	JRL 2389
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1163266-002	Excess (\$)	0.00
	Assign From	Theresa Vimala	Assign Date	15/03/2022
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer -		Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Description of Damages			
5.	General Information			
	Accident Date	25/02/2022	Inspection Date	16/03/2022
	Survey held at	PROJECT 8 MOTORWORKS		
	61 WOODLANDS INDUSTRIAL PARK E9, #01-03, E9 PREMIUM, SINGAPORE 757047			
5a.	a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			
	C) ENCLOSED PL	EASE FIND DAMAGED VEHICLE	PHOTOGRAPHS.	