



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CS/LPC22002420/Evy3n2

Date: 06/05/2022

Code: LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 8778S
Policy No.		Coverage (\$)	0.00
Claim No.	21/22/22/VC00/025550	Excess (\$)	3,200.00
Assign From	GERALD POH	Assign Date	15/03/2022

2. Vehicle Particulars & Condition

Make & Model	ISUZU NNR85	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JAANNR85HE7100050	Colour	WHITE
Odometer	337355 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	4 mm
L/H Front Tyre	195 R15C	DUNLOP	4 mm
R/H Rear Tyre	195 R15C	DUNLOP	4 mm
L/H Rear Tyre	195 R15C	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/03/2022	Inspection Date	16/03/2022
Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		

5a. Remarks

A)THE MARKET VALUE IS S\$33,000.00 (EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**