

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22002422/RQY3E2

Date: 05/05/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00042942102
Claimant Vehicle No : SGU6851C **Insured Vehicle No :** GBC5450L
Date of Loss: 13/03/2022 Nature of Claim: TP Claim No: SNM22D201784/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGU6851C**
Make & Model: HONDA JAZZ, 1.4 (A) Engine No: L13A54001715
Reg. Date: 22/05/2007 (Man. Year: 2007) Chassis No: JHMGD18507S221928
Colour: Blue Odometer: 265418 km
Engine Capacity: 1339 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 15/03/2022
Date Inspected: 16/03/2022 Inspected At: Hiap Lek Automobile Trading
160 Sin Ming Drive #05-17 Sin Ming Autocity
Singapore 575722
Estimated Period of Repair: 0.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value :	\$ 1,000.00
OMV :	\$13,940.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$25,333.00
COE Rebate (2) :	\$ 939.00
Total Rebate (1) + (2) = :	\$ 939.00

The total amount incurred will be Market Value \$1,000.00 minus Total Rebate \$939.00 = \$61.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 May 2022)
Parts:	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU6851C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >