

Steve (LKK) m n
16/3/22, 10.10.22 LIS
My L L My
8 45

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697
Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L
GST:53360061L

QT22/CB8385R/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

QUOTATION

Dear Sir,

Cost of Repair to Vehicle CB8385R

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Rear taillamp assy RH / <i>Q</i> <i>CVT</i>	1	1,850.00	1,850.00
2.	Rear Taillamp RH outer panel / <i>OR</i>	1	2,880.00	2,880.00
3.	Rear RH last compartment panel / <i>OD</i>	1	1,650.00	1,650.00
4.	Rear RH last compartment grille X	1	550.00	550.00
5.	Rear RH last compartment inner structure / <i>OD</i>	1	780.00	780.00
6.	Rear RH last compartment outer lock / <i>OT</i>	1	285.00	285.00
7.	Rear RH last compartment rubber moulding / <i>CR4</i>	1	105.00	105.00
8.	Sealant / <i>MC</i>	5	40.00	200.00
9.	Remove & refit rear RH last pc side glass to assist repair	1	300.00	300.00 <i>250</i>
10.	Remove & refit rear windscreen to assist repair	1	400.00	400.00 <i>300</i>
11.	Remove & refit rear RH inner trims, seats, upholstery etc to assist repair	1	300.00	300.00 <i>250</i>
12.	Check wiring	1	50.00	50.00 <i>30</i>
13.	Apply anti rust	1	100.00	100.00 <i>30</i>
14.	Spray painting	1	2,400.00	2,400.00 <i>1800</i>
15.	Labour charges	1	1,800.00	1,800.00 <i>1500</i>
SUB-TOTAL				SS\$13,650.00

- Price before 7% gst

Thank you.

Yours faithfully,


Winnie Chai

HP: 9850-9666

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: