



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: jeslyn@carzauto.com.sg Tel: 65 6493 1924 Fax: 65 6493 1928

Insurance Company:	China Taiping Insurance (Singapore) Pte Ltd Motor Claims Department		
Address:	3 Anson Rd #16-00 Springleaf Tower Singapore 079909		
Telephone:		Fax:	
Make/ Model :	TOYOTA HARRIER ELEGANCE 2.0 CVT	Date:	15/3/2022
Chassis No :	ZSU600137134	Vehicle No:	GBJ2282M
Date/Time of Accident :	12/3/2021 17:20		

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	TAIL GATE <i>St</i>	1	\$ 1,120.00	25%	\$ 840.00 ✓
2	TAIL GATE LOGO <i>new</i>	1	\$ 55.00	25%	\$ 41.25 ✓
3	TAIL GATE LAMP LH <i>com</i>	1	\$ 650.00	25%	\$ 487.50 ✓
4	TAIL GATE LAMP RH <i>X n</i>	1	\$ 650.00	25%	\$ 487.50 X
5	TAIL LAMP LH <i>3? com</i>	1	\$ 585 1,400.00	25%	\$ 1,050.00 <i>438.75</i>
6	TAIL LAMP RH <i>X n</i>	1	\$ 1,400.00	25%	\$ 1,050.00 X
7	REAR BUMPER <i>de</i>	1	\$ 780.00	25%	\$ 585.00 ✓
8	REAR BUMPER SIDE RETAINER LH <i>X n</i>	1	\$ 35.00	25%	\$ 26.25 X
9	REAR BUMPER SIDE RETAINER RH <i>X n</i>	1	\$ 35.00	25%	\$ 26.25 X
10	REAR BUMPER LOWER COVER <i>scr</i>	1	\$ 280.00	25%	\$ 210.00 ✓
11	REAR BUMPER REFLECTOR LH <i>X n</i>	1	\$ 55.00	25%	\$ 41.25 X
12	REAR BUMPER REFLECTOR RH <i>X n</i>	1	\$ 55.00	25%	\$ 41.25 X
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 4,886.25

2602.50

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$	FINAL PRICE \$
1	REAR NUMBER PLATE WITH BRACKET <i>X n</i>	1	\$ 50.00	\$ 50.00 X
2	REAR BUMPER CLIPS <i>new</i>	10	\$ 50.00	\$ 30 50.00
TOTAL SPECIAL NETT ITEM				\$ 100.00

30

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW <u>REAR</u> DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 1,400.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00

Labour Works

Job Scope	Quotation
TO REMOVE/ REFIX WIRING CHECKS	\$ 30 60.00
TO TUFFCOAT AFFECTED AREA	\$ 60 120.00
TO REMOVE AND REFIX <u>REAR</u> WINDSCREEN	\$ 120 150.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 60 120.00
TO REMOVE AND REPLACE TAIL GATE MECHANISM	\$ 80 300.00
OTHER LABOUR COST	\$ 750.00

GRAND TOTAL \$ 8,736.25

Jeslyn

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
 Job Title: Motor Claim
 Mobile: 65 9380 9969
 Email: jeslyn@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Resue
 Hp 90010068
 5 days
 4s
 16/03/22 @ 1415
 Resy after repair

2602.50
 30.00
 900.00
 350.00

 3882.50
 20%
 3106

4s - 3,100