

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Mar 2022)
 Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM2784K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Hui Rong

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Bumper, front <i>Delud</i>	0.00	0.00	✓ *250.00 F
2	1		Fender RH, front <i>Delud</i>	0.00	0.00	✓ *220.00 F
3	1		Headlamp RH <i>Delud</i>	0.00	0.00	✓ *270.00 F
4	1		*Front bumper retainer, RH <i>Delud</i>	0.00	0.00	✓ *55.00 F
5	1		*Front fog lamp cover, RH <i>at</i>	0.00	0.00	✓ *60.00 F
6	1		*Front fender cowl, RH <i>Delud</i>	0.00	0.00	✓ *110.00 F

F=Franchise part.

Sub Total (S\$)

965.00

+ Margin on L,N Items 15.00% (S\$)

144.75

Total Parts (S\$)

1,109.75

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

965

1109.75

Estimates on Miscellaneous Items

Supplementary

No Qty Particulars

Amount

Miscellaneous Items

1	1	Front bumper clips	RM
2	1	Front fender cowling clips RH	RM

30	60.00
30	60.00

Sub Total (S\$)

120.00

60

Estimates on Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove and replace the abovementioned parts. To knock out accident dented portion and cutting welding works.	New ✓ 400	600.00
2	To spray painting	New ✓ 400	600.00
3	To check wiring	New ✓	25.00
4	To check wheel alignment	New ✓ 80	100.00
905 Gross Labour Cost (\$)			1,325.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian Li
P/P 26/03/22.
04 days.

total: 2074.75 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

