



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22002445/Aty3n2 Date: 15/06/2022 Code: AIS	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SNC 8561M	Veh. Inspected	SLA 7753S
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004219/FQ	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	16/03/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MERCEDES BENZ E200	c.c	1796
	Engine No.	HIDDEN	Year of Reg.	2007
	Chassis No.	WDB2110412B038699	Colour	SILVER
	Odometer	244148 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	225/55 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	225/55 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/55 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/55 R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	12/03/2022	Inspection Date	17/03/2022
	Survey held at	PREMIUM CARZ SERVICES PTE LTD 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	