



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS/ASM22002454/Gqy3	
			Date: 16/03/2022	
			Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2325U		Veh. Inspected	GBE 8486D
Policy No.			Coverage (\$)	0.00
Claim No.	S2M03VRE		Excess (\$)	0.00
Assign From	ONG Kian Theng Derick		Assign Date	16/03/2022
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	11/03/2022		Inspection Date	17/03/2022
Survey held at	Blk 1 Kaki Bukit Ave 6 #01-08 Autobay (S) 417883			
Repairer	TSL AUTO GARAGE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				