



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA			Ref: CC4/ASM22002458/Upa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1313R	Veh. Inspected	SMZ 1574M	
Policy No.	P2465679	Coverage (\$)	0.00	
Claim No.	S2M03VTR	Excess (\$)	0.00	
Assign From		Assign Date	16/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI CN7 AVANTE (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	KMHLN41ETNU137118	Colour	BLUE	
Odometer	30859 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KAPSEN	8 mm	
L/H Front Tyre	205/55 R16	KAPSEN	8 mm	
R/H Rear Tyre	205/55 R16	KAPSEN	8 mm	
L/H Rear Tyre	205/55 R16	KAPSEN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/03/2022	Inspection Date	16/03/2022	
Survey held at	39 Woodlands Close, MEGA@Woodlands #01-24, S737856			
Repairer	NINETEEN AUTOWERKS PTE. LTD.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	