

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd DATE: 13/4/2022

Survey details

Date of loss	14/3/2022
Date of appointment	16/3/2022
Date of survey	11/4/2022
Location of survey	JL AUTO SERVICES PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle number	GBK 5850Z
Make and Model	TOYOTA DYNA 150 5MT
Date of registration	23/9/2020
Excess	
Market Value	\$81,000.00
Parf Rebate	\$21,116.00
Nett Loss	\$59,884.00

Repair details

T 10 1 T 0	
nitial Estimate	

Proposed/Revised repair cost:

Parts	
"Check items (Estimated)	
Labour	
Total	
Lump Sum (Estimated)	

Number of days of repair 2 days (est)

Remarks: Damages Consistent

The estimated repair cost of the damaged vehicle is in the region of 1,000.00-2,000.00