




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM22002464/Vvy3e2 Date: 29/04/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SHF 564M	Veh. Inspected	GBK 5850Z	
Policy No.	VFX/P2413997	Coverage (\$)	0.00	
Claim No.	S2M03VOL	Excess (\$)	0.00	
Assign From	CHAN KIAN CHUAN	Assign Date	16/03/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTFAT35YX0K215330	Colour	SILVER	
Odometer	75285 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	14/03/2022	Inspect Date / Time	11/04/2022 ( 05:30 PM )	
Survey held at	JL AUTO SERVICES PTE LTD BLK 3006 UBI ROAD 1 #01-346 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		

Report Ref No. CS3/ASM22002464/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.