

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 7082R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HEAD LAMP LH	CRACKED	760.80	760.80
1	FRONT BUMPER	DEFORMED	584.40	584.40
1	FRONT BUMPER SIDE GRILLE LH	NOT NECESSARY	81.10	-
1	FRONT BUMPER RETAINER LH	NECESSARY	121.10	121.10
1	FRONT BUMPER SIDE BRACKET LH	NOT NECESSARY	49.00	-
1	FRONT BUMPER TOP BRACKET	NOT NECESSARY	126.50	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,695.80	-
1	FRONT DOOR CHECKER LH	NOT NECESSARY	86.50	-
2	FRONT DOOR HINGE	NOT NECESSARY	191.00	-
1	FRONT DOOR LOCK LH	NOT NECESSARY	321.00	-
1	FRONT DOOR PILLAR LH	TO REPAIR SEE LABOUR	855.50	-
1	FRONT STEP GARNISH LH	CUT	165.70	165.70
1	FRONT STEP PANEL LH	TO REPAIR SEE LABOUR	145.20	-
	LESS 25% DISCOUNT		-1,295.90	-408.00
			3,887.70	1,224.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	60.00	30.00
1	FRONT DOOR LETTERING (SN)	NECESSARY	50.00	30.00
1	FRONT BUMPER SIDE SKIRT LH (SN)	DEFORMED	350.00	280.00
			460.00	340.00
	<u>LABOUR</u>			
	TO DO COMPUTERIZED WHEEL ALIGNMENT	NOT NECESSARY	120.00	-
	TO TRANSFER FRONT DOOR MECHANISM	NOT NECESSARY	120.00	-
	TO APPLY UNDERCOATING		100.00	50.00
	TO PANEL BEATING, REMOVE & REFIT PARTS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH, FRONT DOOR PILLAR LH AND FRONT STEP PANEL LH.		900.00	400.00

Report Ref No. CS/AGI22002469/Aty3h2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO SPRAY PAINTING		800.00	550.00
			2,040.00	1,000.00
	GRAND TOTAL		6,387.70	2,564.00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22002469/Aty3h2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.