

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

9531
ATA 565825

Veh No:

SLJ1725

Yr Regn:

25/11/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Land Rover Evoque c.c. 1999

Colour:

Brown

A/C: Insured / Std / NI / NA

Sp. Reading

32558

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SALVALAG 26-H14552

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

235/60 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

06/3/22

D.O.I.

22/3/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20p 1812.

29/3/22 1/5 @ 4100 informed willian

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS.)

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

AlGAsia Insured's Veh No : SLK6968T
Date of Accident : 06 March 2022



陳林學呀私人有限公司

TAN L M MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Miss Manisha Rajesh Sheth

Date : 09 March 2022

Estimate To Repair SLJ172S - Land Rover RANGE ROVER EVOQUE 2.0 TSS SR

Chassis No : SALVA2AG2GH145152

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	o/s front door <i>R</i>	\$ 2,254.08 <i>X</i>
02	1 pc	o/s front door garnish with silver moulding <i>R</i>	\$ 250.50 <i>X</i>
03	1 pc	o/s front door weatherstrip <i>11</i>	\$ 268.39 <i>X</i>
04	1 pc	o/s rear door <i>Bodywork</i>	\$ 2,654.98 <i>2545.00</i>
05	1 pc	o/s rear door garnish with silver moulding <i>cut/cut</i>	\$ 250.50
06	1 pc	o/s rear door weatherstrip <i>new</i>	\$ 268.39
07	1 pc	o/s rear door arch <i>grated</i>	\$ 315.10 <i>288.00</i>
08	1 pc	o/s front door outer top moulding <i>11</i>	\$ 175.45 <i>X</i>
09	1 pc	o/s rear door outer top moulding <i>new</i>	\$ 175.45
		Less 10 %	\$ 6,612.84
			\$ 661.28
			\$ 5,951.56
<u>SPECIAL NETT ITEMS</u>			
10	1 pc	o/s sport rim <i>front Rear cut</i>	\$ 1,500.00 <i>800 s/w</i>
11	1 pc	o/s tyre <i>front Rear</i>	\$ 350.00 <i>X</i>
			\$ 1,850.00
<u>LABOUR & MISC. CHARGES</u>			
01		Putty and spray painting o/s front & rear side door of the affected portion.	\$ 900.00 <i>600</i>
02		Panel beating, knocking and straighten o/s front & rear side the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 800.00 <i>400</i>
03		To rust-proofing of the affected areas.	\$ 150.00 <i>30</i>
04		To transfer o/s front & rear door fittings and perform water seepage test.	\$ 200.00 <i>60</i>
05		To check electrical lighting concerned.	\$ 50.00 <i>20</i>
06		remove and reinstall o/s tyre & rim	\$ 50.00 <i>40</i>
			\$ 2,150.00
		Total	\$ 9,951.56

not Allowed
4400

2/5
22/3/22
Wright Affix -
4 days

P- 352734
102
317460
512460
6099