



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS6/AIS22002476/Tvy3 Date: 17/03/2022 Code: AIS	
1. Policy Particulars :- OWN DAMAGE (DESKTOP SURVEY)				
	Insured Veh.	Veh. Inspected	SND 6030L	
	Policy No.	Coverage (\$)	0.00	
	Claim No. 2022 22004226/SL	Excess (\$)	0.00	
	Assign From SHANTI	Assign Date	17/03/2022	
2. Vehicle Particulars & Condition				
	Make & Model	c.c	0	
	Engine No. HIDDEN	Year of Reg.		
	Chassis No.	Colour		
	Odometer -	Steering		
	Brakes	Modification		
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date 11/03/2022	Inspection Date	17/03/2022	
	Survey held at	56 LOYANG WAY, #04-04 LOYANG ENTERPRISE BUILDING		
	Repairer	AP AUTOMOTIVE SERVICES PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			