

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM <i>62563561 - Yan LKK</i> <i>Survey on 18/3/22 10am</i>		S1000020 / TPCLAIM	Ms Chia Li Li (Xie Lili)				
		Document No. 0	116 Jalan Kelichap				
		Document Date 14/03/2022	Singapore 534320				
			Mobile: 91012673				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 / 80.00	
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50 /	
3	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50 /	
4	B	BP-LAB3 TO CONDUCT ADJUSTMENT ON WAVE RADAR SENSOR. (NETT)				216.50 /	
5	B	BP-LAB3 TO CONDUCT ADJUSTMENT ON FRONT CAMERA FOWARD RECOGNITION. (NETT)				866 / 1082.50	
6	B	BP-LAB3 REMOVE/REPLACE FRONT BUMPER COVER AND REALIGN. <i>866</i>				742 / 927.50	
7	B	BP-RES3 SPRAY PAINT ON FRONT BUMPER COVER. <i>742</i>				96.00 /	
8	L	BP-LPO SUPPLY REGN PLATE (PO#) <i>IT</i> FRONT (NETT)					

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Parts Labour Sublet Lubrication/Fluid Others	Less
<p><i>LKK Auto Consultants hence notify the Repairer of the following:</i></p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 			Amount Due
<p>Acknowledged by Repairer Signature: Date:</p>			Customer Copy

Inchcape

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No.2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Chia Li Li (Xie Lili)				
		Document No.	116 Jalan Kelichap				
		0	Singapore 534320				
		Document Date	Mobile: 91012673				
		14/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTHY65BH202056087	M20AN160600	60	Wally Tan G H	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	B	BP-LAB3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				866.00	
10	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)				480.00	
11	B	BP-LAB3 TRANSFER BACK DOOR COMPONENT AND MECHANISM TO NEW DOOR SHELL. (NETT)				866.00	
12	B	BP-LAB3 REMOVE/REFIX REVERSE CAMERA. (NETT)				216.50	
13	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				216.50	
14	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50	
15	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				433.00	
16	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN REAR PANEL, SPARE WHEEL PAN, R/R AND L/R BODY PANELS, CUT AND WELD PANEL AND FIT NEW PARTS.	866 x 3	2.5		4330.00	
17	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	742 x 2.5	2.5		4081.00	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet				
			Lubrication/Fluid				
			Others		Amount Due		

Customer Copy

ESTIMATE

Account Details		Account No.	Customer Details				
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Ms Chia Li Li (Xie Lili)				
		Document No.	116 Jalan Kelichap				
		0	Singapore 534320				
		Document Date	Mobile: 91012673				
		14/03/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	0.00		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
18	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00	
19	S	BP-SUBLET TO RESET ECU & REPROGRAMME. (NETT)				216.50	
20	L	BP-LPO SUPPLY REGN PLATE (PO#)				96.00	
21	1	REAR (NETT)	1.00	140.90		140.90	
22	2	L53395-76030 SEAL, HOOD TO FR END	1.00	1311.00		1311.00	
23	3	L53101-76320 GRILLE SUB-ASSY.	1.00	1082.90		1082.90	
24	4	L53141-53041 GARNISH, RADIATOR	1.00	225.50		225.50	
25	5	L53114-76010 GRILLE, RADIATOR	1.00	83.00		83.00	
26	6	L52115-76020 SUPPORT, FR BUMPER	1.00	83.00		83.00	
27	7	L52116-76020 SUPPORT, FR BUMPER	1.00	133.20		133.20	
28	8	L52521-76010 RETAINER, FR BUMPER	1.00	106.00		106.00	
29	9	L52611-76080 ABSORBER, FR BUMPER	1.00	148.20		148.20	
30	0	L52614-76010 ABSORBER, FR BUMPER	1.00	362.40		362.40	
31	1	L52614-76010 EXTENSION, FR	1.00	362.40		362.40	
32	2	L52112-76902 EXTENSION, FR	2.00	55.50		111.00	
33	3	L75895-53010 TAPE, MOULDING, NO.1	1.00	42.50		42.50	
34	4	L16562-24020 SEAL, RADIATOR TO	1.00	42.50		42.50	
35	5	L16563-24020 SEAL, RADIATOR TO	1.00	64.20		64.20	
36	6	L52125-76050 BRACKET, FOG LAMP	1.00	64.20		64.20	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour		Amount Due		
			Sublet				
			Lubrication/Fluid				
			Others				

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili)			
			Document No. 0		116 Jalan Kelichap			
			Document Date 14/03/2022		Singapore 534320 Mobile: 91012673			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MZA10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
37	7	L81481-76070	COVER, FOG LAMP, RH <i>n x nn</i>			1.00	145.00	145.00
38	8	L81482-76070	COVER, FOG LAMP, LH <i>n x nn</i>			1.00	145.00	145.00
39	9	L52411-76010	GUARD, FR BUMPER <i>BR</i>			1.00	411.10	411.10
40	0	L52114-76260	BRACKET, FR BUMPER <i>(sample plate with) - BR</i>			1.00	170.70	170.70
41	1	L89348-12070 B5	RETAINER, ULTRASONIC <i>ns</i>			1.00	44.10	44.10
42	2	L89348-12140 B5	RETAINER, ULTRASONIC <i>ns</i>			1.00	44.10	44.10
43	3	L75392-35220	RETAINER OUTSIDE <i>ne</i>			1.00	4.20	4.20
44	4	T90467-07215	CLIP <i>ne</i>			15.00	2.70	40.50
45	5	L58307-76050	PANEL SUB-ASSY, BODY <i>n end panel take photo copy</i>			1.00	921.40	921.40
46	6	L52599-76010	STOPPER, RR BUMPER <i>n x nn (photo)</i>			2.00	8.10	16.20
47	7	L68105-76900	GLASS SUB-ASSY, BACK <i>ns</i>			1.00	1395.30	1395.30
48	8	L75573-76020	MOULDING, BACK <i>ne</i>			1.00	34.30	34.30
49	9	T62785-60030	SPACER, QUARTER <i>ne</i>			5.00	6.20	31.00
50	0	L67005-76240	PANEL SUB-ASSY, BACK <i>(Tailgate) - nn</i>			1.00	6452.00	6452.00
51	1	T04562-12010	W/SCREEN DAM KIT, <i>ne</i>			1.00	128.50	128.50
52	2	T21000-20	SIKA 182010 SIKA TACK GO! (BLA <i>ne</i>			2.00	108.00	200.00
53	3	T21000-22	SIKA 207. G+P ADHESIVE PRIMER <i>ne</i>			1.00	200.00	200.00
54	4	L69326-76010	PLATE, BACK DOOR <i>n x nn</i>			1.00	151.40	151.40
55	5	L867D0-76010	CAMERA ASSY, <i>n x nn</i>			1.00	1358.70	1358.70
56	6	L75441-76030	PLATE, BACK DOOR <i>ne (logo)</i>			1.00	72.30	72.30
For & on behalf of			Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No 2 Pandan Crescent

Singapore 128462, Tel no. 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili)		
			Document No.		116 Jalan Kelichap		
			0		Singapore 534320		
			Document Date		Mobile: 91012673		
			14/03/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
57	7	L90975-02228 EMBLEM - AC	1.00	193.40		193.40 ✓	
58	8	L75442-76030 PLATE, BACK DOOR (logs) - AC	1.00	72.30		72.30 ✓	
59	9	L64716-76030 CO COVER, DECK TRIM, RR	1.00	266.20		266.20 ✓	
60	0	L52575-76020 RETAINER, RR BUMPER	1.00	179.30		179.30 ✓	
61	1	L52576-76020 RETAINER, RR BUMPER	1.00	179.30		179.30 ✓	
62	2	L52023-76030 REINFORCEMENT	1.00	441.60		441.60 ✓	
63	3	L52591-76020 SEAL, RR BUMPER	1.00	90.10		90.10 ✓	
64	4	L52592-76020 SEAL, RR BUMPER	1.00	90.10		90.10 ✓	
65	5	L52159-76920 COVER, RR BUMPER	1.00	844.40		844.40 ✓	
66	6	L75895-53010 TAPE, MOULDING, NO.1	2.00	55.50		111.00 ✓	
67	7	L52169-76081 COVER, RR BUMPER, - AC (lower) DO	1.00	456.70		456.70 ✓	
68	8	L52162-76040 PLATE, RR BUMPER, - AC	1.00	18.40		18.40 ✓	
69	9	T90950-06124 TAPE, SEAL - AC	2.00	5.20		10.40 ✓	
70	0	L75392-35220 RETAINER OUTSIDE - AC	9.00	4.20		37.80 ✓	
71	1	S52161-0K040 BUMPER CLIPS - AC	13.00	4.30		55.90 ✓	
72	2	L89348-12070 B5 RETAINER, ULTRASONIC - AC	2.00	44.10		88.20 ✓	
73	3	L89348-12140 B5 RETAINER, ULTRASONIC	2.00	44.10		88.20 ✓	
74	4	L89341-33220 B4 SENSOR, ULTRASONIC	4.00	490.80		1963.20 ✓	
75	5	L81671-76010 LENS & BODY, BACK-UP	1.00	202.60		202.60 ✓	
76	6	L81681-76010 LENS & BODY, BACK-UP	1.00	202.60		202.60 ✓	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		
					Others		Amount Due

Customer Copy



Borneo Motors



Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No 2 Pandan Crescent

Singapore 128462, Tel no : 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Chia Li Li (Xie Lili)		
			Document No.		116 Jalan Kelichap		
			0		Singapore 534320		
			Document Date		Mobile: 91012673		
14/03/2022							
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MZAH10R	AWXBB S2	06/04/2020	SKT9026G	0	20824	64TP/SKT9026G/120322
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHY65BH202056087		M20AN160600	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description		Qty	Unit Price	Disc %	Amount
77	7	L81676-76010	RIM, BACK-UP, RH	1.00	16.00		16.00
78	8	L81686-76010	RIM, BACK-UP LAMP, RH	1.00	16.00		16.00
79	9	L8158A-12260	LED, RR LAMP, RH	2.00	186.50		373.00
80	0	L81910-76010	REFLECTOR ASSY, X	1.00	51.60		51.60
81	1	L81920-76010	REFLECTOR ASSY, X	1.00	51.60		51.60
82	2	L66259-76010	COVER, RR BODY	1.00	320.20		320.20
83	3	L58398-76010	COVER, FLOOR UNDER, X	1.00	170.70		170.70
84	4	L58399-76010	COVER, FLOOR UNDER, X	1.00	170.70		170.70
85	5	L75605-76010	MOULDING SUB-ASSY, X	1.00	387.50		387.50
86	6	L75606-76010	MOULDING SUB-ASSY, X	1.00	387.50		387.50
87	7	T90467-07220	CLIP - APC	2.00	2.70		5.40
				<p>STER (LKK) 18/3/22, 12.00</p> <p>WL PL 9/11 dgs (end PL PL) P/P hy PL hy</p>			
For & on behalf of		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd						39,169.20	
		Please acknowledge receipt of vehicle		Parts		GST 7.00%	
				Labour		2,741.84	
				Sublet		Less	
				Lubrication/Fluid		0.00	
				Others		Amount Due	
						41,911.04	

Customer Copy