

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST Reg No. 201629438M

16/03/2022

Owner: HYMS CAR LEASING PTE LTTD

ESTIMATE TO REPAIR HONDA FREED HYBRID - SMN8604C

1pc	rear tailgate	1207.90	By	\$	1,207.90	✓
1pc	rear tailgate "H" logo		re	\$	68.20	—
1pc	rear tailgate "FREED" emblem		re	\$	58.00	—
1pc	rear tailgate windscreen moulding	121	re	\$	181.80	✓
1pc	rear tailgate outer chrome	321.70	mgcm	\$	385.50	✓
1pc	rear tailgate inner garnish		mgcm	\$	265.30	✓
1pc	rear tailgate inner lock	187.50	re	\$	287.50	✓
1pc	rear tailgate inner rubber		re	\$	195.50	X
1pc	rear tailgate inner handle		re	\$	47.50	X
2pcs	rear taillamp lower bracket @\$85.50		re	\$	171.00	X
1pc	rear bumper	828.90	re	\$	991.20	—
2pcs	rear bumper side retainer @\$181.25		re	\$	362.50	X
1pc	rear bumper towing cover		re	\$	58.50	X
2pcs	rear bumper centre beam @\$180.50		re	\$	361.00	X
1pc	rear end panel		re	\$	623.70	X
1pc	rear end panel inner garnish		mgcm	\$	100.90	✓
				\$	5,366.00	
				\$	1,073.20	
				\$	4,292.80	
	less 20%					
1set	rear parking sensor		s.nett	\$	280.00	200.00
1set	rear number palte & casing		s.nett	\$	50.00	X
	remove & refix rear windscreen glass			\$	120.00	✓
	tuffkote			\$	80.00	301
	sealant			\$	80.00	401
	wiring			\$	100.00	201
	spray painting			\$	1,000.00	8001
	labour charges			\$	1,000.00	5001
	Total			\$	7,002.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

